



- Suppression Repair Points**
- PointType, Repair Status
 - Ridge Repair Needed
 - Chipping Blank Repair Needed
 - Culvert Damage, Repair Needed
 - Culvert Damage, Completed - Approved
 - Clear Patch Repair Needed
 - Clear Patch, Completed - Approved
 - Drop Point Repair Needed
 - Drop Point, Completed - Approved
 - Equipment Fault Repair Needed
 - Fence Damage Repair Needed
 - Fence Damage, Completed - Approved
 - Gate Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree Repair Needed
 - Hazard Tree, Repair Needed
 - Log and Scatter Trees Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Machine Damage Repair Needed
 - Machine Damage, Repair Needed
 - Other Repair Needed
 - Other, Completed - Approved
 - Relevant Track Repair Needed
 - Relevant Track Repair, Repair Needed
 - Road Needs Repair Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing Repair Needed
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Crossing Location Repair Needed
 - Water Crossing Location, Repair Needed
 - Waterbar Repair Needed
 - Waterbar Repair, Completed - Approved

SUPPRESSION REPAIR, 09/18/18
Div K

SoCal IMT 3 GIS
September 17, 2018
2310

Miles
0 0.25 0.5 1

Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 18, 2018
SUPPRESSION REPAIR
Div K

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- Other State Lands
 - USDA Forest Service
 - Bureau of Reclamation
 - Bureau of Land Management
 - Bureau of Indian Affairs
 - Other Federal Lands
- Other Symbols**
- Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w/ weight limit)
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area

Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/18/18
Div K

SUPPRESSION REPAIR, 09/18/18
Div K