



- Suppression Repair Points**
- Ridge Repair Needed
 - Chipping Blows Repair Needed
 - Culvert Damage Repair Needed
 - Culvert Damage Completed - Approved
 - Clear Push Repair Needed
 - Clear Push Completed - Approved
 - Drop Pile Repair Needed
 - Equipment Failure Repair Needed
 - Equipment Failure Repair Needed
 - Fence Damage Repair Needed
 - Fence Damage Completed - Approved
 - Gate Repair Needed
 - Gate Completed - Approved
 - Hazard Tree Repair Needed
 - Hazard Tree Repair Needed
 - Log and Scatter Trees Repair Needed
 - Mechanical Damage Repair Needed
 - Other Repair
 - Other Repair Needed
 - Other Completed - Approved
 - Rehabilitated Road Repair Needed
 - Road Needs Repair Repair Needed
 - Road Needs Repair Completed - Approved
 - Water Course Crossing Repair Needed
 - Water Course Crossing Completed - Approved
 - Water Course Crossing Repair Needed
 - Water Course Crossing Completed - Approved
 - Water Drafting Location Repair Needed
 - Water Drafting Location Repair Needed
 - Water Drafting Location Completed - Approved

Road Class shown in fuchsia. Not all roads show Road Class values

Mendocino Complex
 CA-MEU-008674
 September 20, 2018
SUPPRESSION REPAIR
 Div H

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w weight limit)
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area
 - USDA Forest Service

SUPPRESSION REPAIR, 09/20/18
 Div H

QR Code

Miles

0 0.25 0.5 1

Datum: NAD 83

SUPPRESSION REPAIR, 09/20/18
 Div H

SUPPRESSION REPAIR, 09/20/18
 Div H