


- Suppression Repair Points**
- PointType, Repair Status**
- Ridge, Repair Needed
 - Cheeping Blain, Repair Needed
 - Culvert Damage, Completed - Approved
 - Deer Funnel, Repair Needed
 - Deer Funnel, Completed - Approved
 - Drop Point, Repair Needed
 - Equipment Faults, Repair Needed
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Helispot, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Machine Damage, Repair Needed
 - Other - Main
 - Other, Repair Needed
 - Other, Completed - Approved
 - Rebarbed Truck Floor, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing - Main
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Crossing Location, Repair Needed
 - Waterstar Needed, Repair Needed
 - Waterstar Needed, Completed - Approved



Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/21/18
Div F/G

NorCal IMT 1 GIS
September 20, 2018
2104

Miles
0 0.25 0.5 1

Datum: NAD 83



Mendocino Complex
CA-MEU-008674
September 21, 2018
SUPPRESSION REPAIR
Div F/G

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Repair Needed
 - Unknown
 - Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w/ weight limit)
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area
- Ownership**
- USDA Forest Service

SUPPRESSION REPAIR, 09/21/18
Div F/G

SUPPRESSION REPAIR, 09/21/18
Div F/G