



- Suppression Repair Points**
 Point Type Repair Status
- Ridge Repair Needed
 - Chipping Blows Repair Needed
 - Culvert Damage, Completed - Approved
 - Culvert Damage, Repair Needed
 - Clear Flush, Repair Needed
 - Clear Flush, Completed - Approved
 - Deep Pans, Repair Needed
 - Deep Pans, Completed - Approved
 - Equipment Piles, Repair Needed
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Helicopter, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Machine Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Rebarbed Track Pile, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Crossing Location, Repair Needed
 - Water Crossing Location, Completed - Approved
 - Waterbar, Repair Needed
 - Waterbar, Completed - Approved

Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/21/18
Div H



Datum: NAD 83



Mendocino Complex

CA-MEU-008674
 September 21, 2018

SUPPRESSION REPAIR

Div H

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- USDA Forest Service
 - Wilderness Area
 - Rehab Avoidance Area
- Other Symbols:**
- Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w weight limit)

SUPPRESSION REPAIR, 09/21/18
Div H