


- Suppression Repair Points**
- PointType, Repair Status
- Ridge, Repair Needed
 - Chipping Blows, Repair Needed
 - Culvert Damage, Repair Needed
 - Culvert Damage, Completed - Approved
 - Copter Pouch, Repair Needed
 - Copter Pouch, Completed - Approved
 - Drop Point, Repair Needed
 - Drop Point, Completed - Approved
 - Equipment Fault, Repair Needed
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Helispot, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Machine Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Roadside Truck Flip, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing - Null
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Crossing Location, Repair Needed
 - Waterstar Needed, Repair Needed
 - Waterstar Needed, Completed - Approved



Road Class shown in fuschia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/21/18
Div K

NorCal IMT 1 GIS
September 20, 2018
2128

Miles
0 0.25 0.5 1

Datum: NAD 83



Mendocino Complex

CA-MEU-008674
September 21, 2018

SUPPRESSION REPAIR

Div K

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- Other State Lands
 - USDA Forest Service
 - Bureau of Reclamation
 - Bureau of Land Management
 - Bureau of Indian Affairs
 - Other Federal Lands
- Other Symbols:**
- Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area
 - Bridge (w/ weight limit)
 - Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line

SUPPRESSION REPAIR, 09/21/18
Div K

SUPPRESSION REPAIR, 09/21/18
Div K