




- Suppression Repair Points**
- PointType: Repair Status
 - Chipping Blows: Repair Needed
 - Chipping Blows: Completed - Approved
 - Clearing Damage: Repair Needed
 - Clearing Damage: Completed - Approved
 - Clear Push: Repair Needed
 - Clear Push: Completed - Approved
 - Clear Piles: Repair Needed
 - Clear Piles: Completed - Approved
 - Equipment Piles: Repair Needed
 - Equipment Piles: Completed - Approved
 - Force Damage: Repair Needed
 - Force Damage: Completed - Approved
 - Gate: Repair Needed
 - Gate: Completed - Approved
 - Hazard Tree: Repair Needed
 - Hazard Tree: Completed - Approved
 - Helicopter: Repair Needed
 - Helicopter: Completed - Approved
 - Log and Scatter Trees: Repair Needed
 - Log and Scatter Trees: Completed - Approved
 - Mechanical Damage: Repair Needed
 - Mechanical Damage: Completed - Approved
 - Other: Repair Needed
 - Other: Completed - Approved
 - Rehabilitate Truck Point: Repair Needed
 - Rehabilitate Truck Point: Completed - Approved
 - Road Needs Repair: Repair Needed
 - Road Needs Repair: Completed - Approved
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved
 - Water Course Crossing: Multi
 - Water Course Crossing: Repair Needed
 - Water Course Crossing: Completed - Approved
 - Water Drafting Location: Repair Needed
 - Water Drafting Location: Completed - Approved
 - Waterbar Needed: Repair Needed
 - Waterbar Needed: Completed - Approved



Road Class shown in fuchsia. Not all roads show Road Class values

SUPPRESSION REPAIR, 09/25/18
Div F/G



NorCal IMT 1 GIS
September 23, 2018
2156

Datum: NAD 83



Mendocino Complex

CA-MEU-008674
September 25, 2018

SUPPRESSION REPAIR

Div F/G

- Repair Legend**
- Completed - Inspected
 - Completed - Ready for Inspection
 - In Progress
 - No Repair Needed
 - Other - See Comments
 - Repair Needed
 - Unknown
- Ownership**
- Completed Dozer Line
 - Completed Hand Line
 - Road as Completed Line
 - Bridge (w/ weight limit)
 - Direct Protection Areas
 - Wilderness Area
 - Rehab Avoidance Area
 - USDA Forest Service

SUPPRESSION REPAIR, 09/25/18
Div F/G