


- ### Suppression Repair Points
- PointType, Repair Status
- Ridge, Repair Needed
 - Cheating Blain, Repair Needed
 - Culvert Damage, Repair Needed
 - Culvert Damage, Completed - Approved
 - Clear Push, Repair Needed
 - Clear Push, Completed - Approved
 - Drop Point, Repair Needed
 - Equipment Found, Repair Needed
 - Fence Damage, Repair Needed
 - Fence Damage, Completed - Approved
 - Gate, Repair Needed
 - Gate, Completed - Approved
 - Hazard Tree, Repair Needed
 - Hazard Tree, Repair Needed
 - Log and Scatter Trees, Repair Needed
 - Medical Damage, Repair Needed
 - Other, Repair Needed
 - Other, Completed - Approved
 - Rebarbed Truck Point, Repair Needed
 - Road Needs Repair, Repair Needed
 - Road Needs Repair, Completed - Approved
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Repair Needed
 - Water Course Crossing, Completed - Approved
 - Water Drafting Location, Repair Needed
 - Water Needs, Repair Needed
 - Water Needs, Completed - Approved



Road Class shown in fuschia. Not all 16 roads show Road Class values

Mendocino Complex

CA-MEU-008674
September 25, 2018

SUPPRESSION REPAIR

Div I

Repair Legend


- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line

- Direct Protection Areas
- Rehab Avoidance Area

Ownership

- USDA Forest Service
- Bureau of Reclamation
- Bureau of Land Management
- Bureau of Indian Affairs
- Other Federal Lands



NorCal IMT 1 GIS
September 23, 2018
2145

Miles
0 0.25 0.5 1

Datum: NAD 83