



Number	PtType	RepairStatus	DateUpdated	Comments
1	Culvert Damage	Identified for Repair	7/8/2020	18" plastic, may not have been functional prior to fire
2	Water Course Crossing	Identified for Repair	7/8/2020	Hand crew needed to dig out crossing, no excavator.
3	Fence Damage	Identified for Repair	7/8/2020	5 strand barbed wire, approx 20'
4	Fence Damage	Identified for Repair	7/8/2020	
5	Fence Damage	Identified for Repair	7/8/2020	

REPAIR MAP
CREWS INC
CA SCU 004686
07/09/2020
0700 - 0700

0 0.5 1
Miles

1:18,000

IMT 6 GIS
7/8/2020
2342 Hours
NAD 83 Teale Albers

● Dip Site
○ Drop Point
● Helispot
● Landmark
○ Mobile Weather Unit
— Division Break
— Completed Dozer Line
— Completed Hand Line
— Road as Completed Line
— Access or Improved Road
— Suppression Repair
— RepairLineStatus
— RepairStatus
— Identified for Repair
● Culvert Damage
● Water Damage
● Water Course Crossing
● RepairPoint_NeedsRepair
● PtType

SUPPRESSION REPAIR MAP
CREWS INCIDENT
CA SCU 004686
07/09/2020
0700 - 0700

REPAIR MAP
CREWS INC
CA SCU 004686
07/09/2020
0700 - 0700