



Map Number	PtType	RepairStatus	DateUpdated	Comments
1	Culvert Damage	Identified for Repair	7/8/2020	18" plastic, may not have been functional prior to fire
2	Water Course Crossing	Identified for Repair	7/8/2020	Hand crew needed to dig out crossing, no excavator.
3	Fence Damage	Identified for Repair	7/8/2020	5 strand barbed wire, approx 20'
4	Fence Damage	Identified for Repair	7/8/2020	
5	Fence Damage	Identified for Repair	7/8/2020	
6	Fence Damage	Identified for Repair	7/9/2020	Owner (Larry Imas (408) 483-2248) requests temporary "cowboy" gate 5 strand barbed. He will install permanent gate in winter. Non-climb fence does not need replacement
7	Fence Damage	Identified for Repair	7/9/2020	Owner (Larry Imas (408) 483-2248) requests non-climb wire removed from unused cross fence and re-applied at site. Also has 5 strand barbed wire needing repair.
8	Fence Damage	Identified for Repair	7/9/2020	4 strand barb replacement
9	Fence Damage	Completed - READ Approved	7/9/2020	Canada road
10	Fence Damage	Identified for Repair	7/9/2020	Wooden fence needs repair. Barbed wire & t-post
11	Fence Damage	Completed - READ Approved	7/9/2020	fixed
12	Fence Damage	Identified for Repair	7/9/2020	t-post needed
13	Fence Damage	Identified for Repair	7/9/2020	t-post needed

Line Type	Length (mi)		
	Needs Repair	Repaired	Total
Dozer Line	9.63		9.63
Hand Line	1.65		1.65



DISCLAIMER: The displayed incident data is approximate and should only be used for informational purposes. The information contained in supporting base layers was generated from GIS data maintained by different sources and agencies and is not necessarily accurate to mapping, surveying, or engineering standards.

IMT 6 OISS
7/9/2020
2324 Hours
NAD 83 Teale Albers

- Dip Site
- Drop Point
- Helispot
- Landmark
- Mobile Weather Unit
- Division Break
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Access or Improved Road
- Suppression Repair
- RepairLineStatus
- RepairStatus
- Identified for Repair
- RepairPoint_NeedsRepair
- Culvert Damage
- Fence Damage
- Water Course Crossing
- FeatureCat
- Completed Dozer Line
- Completed Hand Line

SUPPRESSION REPAIR MAP
CREWS INCIDENT
CA SCU 004686
07/10/2020
0700 - 0700

