



Total Repair Status for the Delta-Hirz Fire			Percent of Work for Each Fire		
Repair Status by Feature (miles)	Delta	Grand Total	Repair Status by Feature (miles)	Delta	Grand Total
Completed - Ready for Inspection	2.36	2.36	Access or Improved Road	0.39%	0.00%
No Repair Needed	2.61	2.61	No Repair Needed	1.07%	0.00%
Repair Needed	4.54	4.54	Repair Needed	1.63%	0.00%
Unknown	13.32	13.32	Unknown	5.43%	0.00%
Completed Dozer Line	66.80	163.64	Completed Dozer Line	17.44%	10.26%
Other	1.25	1.25	Other	0.00%	0.48%
Completed - Inspected	6.31	24.01	Completed - Inspected	2.41%	1.44%
Completed - Ready for Inspection	4.02	3.03	Completed - Ready for Inspection	1.55%	1.50%
In Progress	5.51	4.94	In Progress	1.85%	1.90%
No Repair Needed	0.61	0.61	No Repair Needed	0.25%	0.00%
Repair Needed	49.06	53.35	Repair Needed	20.14%	20.10%
Unknown	2.76	2.76	Unknown	1.10%	0.14%
Completed Hand Line	15.41	15.72	Completed Hand Line	6.84%	5.27%
Other	0.24	0.24	Other	0.00%	0.00%
Completed - Inspected	1.34	5.60	Completed - Inspected	0.55%	1.38%
Completed - Ready for Inspection	0.42	0.42	Completed - Ready for Inspection	0.17%	0.16%
In Progress	1.84	1.84	In Progress	0.00%	0.71%
No Repair Needed	0.31	0.31	No Repair Needed	0.13%	0.13%
Repair Needed	7.46	5.03	Repair Needed	3.07%	1.53%
Unknown	6.26	10.22	Unknown	2.51%	0.96%
Completed Line	72.04	59.45	Completed Line	29.63%	22.84%
Other	6.13	46.83	Other	2.52%	17.99%
No Repair Needed	19.52	11.17	No Repair Needed	7.71%	6.10%
Management Action Point	42.17	42.17	Management Action Point	0.00%	16.20%
No Repair Needed	42.17	42.17	No Repair Needed	0.00%	16.20%
Other	20.51	41.82	Other	8.45%	16.10%
Completed - Inspected	1.48	1.48	Completed - Inspected	0.00%	0.17%
In Progress	33.12	33.12	In Progress	0.00%	12.76%
Other - See Comments	0.31	0.31	Other - See Comments	0.01%	0.01%
Repair Needed	20.50	7.22	Repair Needed	8.27%	2.77%
Unknown	0.28	0.28	Unknown	0.11%	0.01%
Planned Fire Line	1.44	2.30	Planned Fire Line	0.55%	0.88%
No Repair Needed	1.44	2.30	No Repair Needed	0.55%	0.88%
Planned Secondary Line	0.12	0.12	Planned Secondary Line	0.00%	0.00%
Unknown	0.39	0.39	Unknown	0.00%	0.01%
Proposed Dozer Line	0.39	0.39	Proposed Dozer Line	0.15%	0.00%
Unknown	0.39	0.39	Unknown	0.00%	0.00%
Road as Completed Line	14.81	14.81	Road as Completed Line	14.82%	5.38%
Other	0.59	6.91	Other	0.00%	1.84%
Completed - Inspected	1.41	3.24	Completed - Inspected	0.24%	3.47%
Repair Needed	1.54	1.54	Repair Needed	2.22%	0.00%
Other - See Comments	1.54	1.54	Other - See Comments	1.17%	0.00%
Repair Needed	15.92	19.21	Repair Needed	4.55%	1.26%
Unknown	9.56	9.56	Unknown	3.93%	0.00%
Uncontrolled Fire Edge	8.88	8.88	Uncontrolled Fire Edge	3.65%	0.00%
Other	8.88	8.88	Other	3.65%	0.00%
Grand Total	243.15	243.15	Grand Total	100.00%	100.00%



Suppression Repair
Delta - Hirz Fire
 CA-SHF-001444 - CA-SHF-001223
 09/19/2018

Legend

- Uncontrolled Fire Edge
- Completed Hand Line
- Bridge
- Other
- Stream Crossing
- Repair Needed
- Completed - Inspected
- Completed Line
- Road as Completed Line
- Culverts
- Other Large Dozer Push (parking area, etc.)
- Fuels Removal
- Completed - Ready for Inspection
- Unknown
- Completed Dozer Line
- Other/Road
- Equipment Found
- Road Repair
- In Progress
- Other - See Comments
- USDA FOREST SERVICE
- Fence
- Spring
- Road Repair

