

Suppression Repair Map

Lime Fire
CA-KNF-7074
9/15/2019 Day Shift




Appx 1,872 ac at 2021
09/13/2019

Legend

● Repair Status Point	— Repair Needed	— Planned Secondary Line	■ Other State Lands
● No Repair Needed	— No Repair Needed	— Aerial Hazard	■ USDA Forest Service
● Unknown	— Unknown	— Air Tanker Retardant	■ Bureau of Land Management
— Completed - Inspected	— Completed Line	— Other	■ Other Federal Lands
— Completed - Ready for Inspection	— Completed Dozer Line	— Wildfire Daily Fire Perimeter	
— In Progress	— H - H - Completed Hand Line	— MTCT Ownership	
	— Access or Improved Road	— Fruitgrowers Ownership	

Lime Fire Suppression Repair

	Unknown	No Repair Needed	Repair Needed	In Progress	Completed	Approved	Total Line(mi)
Hand Line	0.34		1.05	8.45	0.78		10.62
Dozer Line	0.16		17.32	3.05	0.88	1.8	23.21
Road	1.31	2.28	7.29	0.6			11.48
Hand Line	3%	0%	10%	80%	7%	0%	
Dozer Line	1%	0%	75%	13%	4%	8%	
Road	11%	20%	64%	5%	0%	0%	45.31



1:15,000

