


Road Repair Assessment

Walker Fire
CA-PNF-001324
September 28, 2019



- Repair Status**
 - Repair Needed (Red line)
 - In Progress (Yellow line)
 - Completed - Ready for Inspection (Orange line)
 - Completed - Inspected (Green line)
 - No Repair Needed (Purple line)
- Road Assessment Standard**
 - Decommissioned (Dark red line)
 - ML 1 - Closed (Red line)
 - ML 2 - High Clearance (Orange line)
 - ML 3 - Passenger Car (Blue line)
 - ML 5 - High Level of Comfort (Light purple line)
 - County Road (Thick orange line)
- Other Features**
 - Culvert (Circle with cross)
 - Dip Site (Blue diamond)
 - Drop Point (Black circle)
 - Dozer Push (Red square)
 - Fence - Cut/Damaged (Dashed line)
 - Hazard (Yellow triangle)
 - Helispot (Blue circle)
 - Repair Point (Purple circle)
 - Road Repair (Black square)
 - Safety Zone (Yellow triangle)
 - Stream Crossing (Blue square)
 - Water Source (Blue circle with 'W')
 - Value at Risk (Black triangle)
 - Zone Break (Black circle with vertical line)
 - Division Break (Black line with parentheses)
 - Completed Dozer Line (Dashed line with cross-hatch)
 - Completed Hand Line (Dashed line with 'H')
 - Road as Completed Line (Dashed line with 'R')

