



Completed Dozer Line		
Repair Status	Length Miles	%
Completed - Inspected	70.17	87.71
Completed - Ready for Inspection	1.58	1.98
In Progress	3.69	4.62
No Repair Needed	0.3	0.37
Repair Needed	3.53	4.42

Completed Hand Line		
Repair Status	Length Miles	
Completed - Inspected	13.82	
In Progress	0.36	
No Repair Needed	0.33	

Supp. Repair

Suppression Repair

Walker Fire

CA-PNF-001324
10/10/2019




Fence - Cut/Damaged	Camp	Incident Command Post	Water Source	Division Break	Completed Dozer Line	Repair Line	Exclusion Zone	Completed - Inspected	In Progress	Known Mine Hazards (Abandoned Mines)
Road Repair	Dip Site	Retardant/Mud Pit	Repair Point	Completed Hand Line	Proposed Dozer Line	Repair Needed	Special Treatment Area	Repair by Hand		
Stream Crossing	Drop Point	Safety Zone	Value at Risk	Road as Completed Line	Planned Fire Line					
Dozer Push	Hellsport	Staging Area	Zone Break	Completed Line	Other					


