



Bridge	Dozer Push	Incident Command Post	Repeater	Staging Area	Aerial Retardant Drop	Road Repair	In Progress	Completed - Inspected	Other - See Comments	Other
Camp	Gate	Internet Access	Retardant in Avoidance Area	Stream Crossing	Completed Dozer Line	Road as Completed Line	No Repair Needed	In Use - Fire Management	Unknown	State
Closure	Hazard	Landmark	Retardant/Mud Pit	Structure Wrap	Completed Hand Line	Uncontrolled Fire Edge	Other - See Comments	Completed - Ready for Inspection	State/cnty/US roads	Interstate
Culvert	Hazard Tree	Landing or Log Deck	Road Repair	Water Source	Contained Line	Completed - Inspected	Other - See Comments	Repair Needed	ROAD_TYPE	US
Dip Site	Helispot	Mobile Weather Unit	Sling Site	Restricted Water Source	Fence	Completed - Ready for Inspection	Repair Needed	No Repair Needed	County	
Drop Point	Hot Spot	Repair Point	Spot Fire	Value at Risk	Access or Improved Road	Repair Line				

0 2 3 6 9 12 15 18 Miles

