


11/8/2020
CA-MNF-000753
AUGUST COMPLEX



		<ul style="list-style-type: none">CampClosetCulvertDip SiteLanding or Log DeckMobile Weather UnitGateHazard TreeHelispotRetardant/Mud PitRoad RepairStaging AreaRepair PointRepairerRetardant in Avoidance AreaRetardant/Mud PitRoad RepairStaging Area	<ul style="list-style-type: none">Stream CrossingWater SourceValue at RiskDivision BreakAccess or Improved RoadRepair LineStream CrossingWater SourceValue at RiskDivision BreakAccess or Improved RoadRepair Line	<ul style="list-style-type: none">Aerial Retardant DropCompleted Doser LineCompleted Hand LineControlled LineFenceAccess or Improved RoadRepair LineRoad RepairRoad as Completed LineUncontrolled Fire EdgeCompleted - InspectedIn ProgressRepair NeededRepair NeededUnknownCompleted - InspectedIn ProgressCompleted - Ready for Inspection	<ul style="list-style-type: none">In ProgressRepair NeededNo Repair NeededUnknownCompleted - InspectedIn ProgressCompleted - Ready for Inspection	<p>State/cnty/US roads</p> <ul style="list-style-type: none">StateCountyOtherState	<p>Road Type</p> <ul style="list-style-type: none">US
--	--	--	---	---	---	---	---

0 1 2 3 4 5 6 Miles

Datum: NAD 1983, UTM, Zone 10