



Repair Status North Zone
August Complex
CA-MNF-000753
4/16/2021



Current as of: 4/16/2021
 NAD83 UTM 21UN



- | | |
|---|--|
| <ul style="list-style-type: none"> ● Aerial Hazard ● Dip Site ● Helispot ● Sling Site ⌋ Division Break ⌋ Zone Break ⌋ Drop Point ⌋ Camp ⌋ Staging Area ⌋ Value at Risk ● Other ● Landmark ● Gate ● Structure Wrap ● Resource Location ● Repair Point ● Hazard Tree ● Fence - Cut/Damaged ● Dozer Push ● Clean Up Area ● Mobile Weather Unit ● Repeater ● Safety Zone ● Hazard ● Water Source ● Restricted Water Source ● Completed Dozer Line ● Completed Hand Line | <ul style="list-style-type: none"> — Planned Secondary Line — Access or Improved Road — Fence — Management Action Point — Other — Repair Line — Road Repair — Escape Route — Contained Line ● Completed - Inspected (44) ● Completed - Ready for Inspection (4) ● In Progress (46) ● Repair Needed (251) ● No Repair Needed (23) ● Other - See Comments (5) ● Unknown (200) ● Completed - Inspected (410) ● Completed - Ready for Inspection (28) ● In Progress (171) ● Repair Needed (485) ● No Repair Needed (210) ● Other - See Comments (10) ● Unknown (188) ● Bureau of Land Management ● Indian Reservation ● State ● Road Type ● County ● Forest |
|---|--|