



Repair Status North Zone
August Complex
CA-MNF-000753
4/24/2021



Current as of: 4/23/2021
 NAD83 UTM 21UN



- | | | | | | |
|---|---|--|--|---|--|
| <ul style="list-style-type: none"> ● Aerial Hazard ● Dip Site ● Helispot ● Sling Site ● Division Break ● Zone Break ● Drop Point ● Staging Area ● Value at Risk ● Other | <ul style="list-style-type: none"> ○ Landmark ○ Gate ○ Bridge ○ Structure Wrap ○ Road Repair ○ Resource Location ○ Repair Point ○ Hazard Tree ○ Fence - Cut/Damaged ○ Fence Push ○ Culvert | <ul style="list-style-type: none"> ● Clean Up Area ● Mobile Weather Unit ● Repeater ● Safety Zone ● Water Source ● Restricted Water Source ● Completed Dozer Line ● Completed Hand Line ● Planned Secondary Line ● Access or Improved Road | <ul style="list-style-type: none"> ■ Fence ■ Management Action Point ■ Other ■ Road Line ■ Road Repair ■ Escapes Route ■ Contained Line ■ Completed - Inspected (123) ■ Completed - Ready for Inspection (3) ■ In Progress (46) ■ Repair Needed (250) | <ul style="list-style-type: none"> ● No Repair Needed (27) ● Other - See Comments (5) ● Unknown (217) ● Completed - Inspected (446) ● Completed - Ready for Inspection (28) ● In Progress (179) ● Repair Needed (476) ● No Repair Needed (212) ● Other - See Comments (10) ● Unknown (202) ● Bureau of Land Management | <ul style="list-style-type: none"> ■ Forest Service ■ Indian Reservation ■ State ■ Roads ○ 0 - Not Maintained ○ 1 - Basic Custodial Care (CLOSED) ○ 2 - 5 (OPEN) ○ Private or County |
|---|---|--|--|---|--|