



Repair Status North Zone

August Complex

CA-MNF-000753

4/28/2021



Current as of: 4/28/2021
NADES UTM 21WN



- | | | |
|---|--|--|
| <ul style="list-style-type: none"> • Aerial Hazard • Dip Site • Sling Site • Division Break • Zone Break • Drop Point • Camp • Restricted Area • Value at Risk • Other • Landmark • Gate • Bridge • Structure Wrap • Road Repair • Resource Location • Repair Point • Hazard Tree • Fence - Cut/Damaged • Dozer Push • Culvert • Clean Up Area • Mobile Weather Unit • Repeater • Safety Zone • Hazard • Water Source • Restricted Water Source • Completed Dozer Line • Completed Hand Line • Access or Improved Road • Fence • Repair Line • Road Repair • Road as Completed Line • Completed - Inspected (35) • Completed - Ready for Inspection (4) • In Progress (10) • Repair Needed (127) | <ul style="list-style-type: none"> • No Repair Needed (6) • Other - See Comments (3) • Unknown (30) • Completed - Inspected (387) • Completed - Ready for Inspection (33) • In Progress (185) • Repair Needed (526) • No Repair Needed (79) • In Progress (10) • Other - See Comments (13) • Unknown (64) | <ul style="list-style-type: none"> • Bureau of Land Management • Forest Service • Indian Reservation • State • Private or County • 0 - Not Maintained • 1 - Basic Custodial Care (CLOSED) • 2 - 5 (OPEN) |
|---|--|--|