



Repair Status South Zone

August Complex

CA-MNF-000753

4/28/2021



Current as of: 4/28/2021
NAD83 UTM Z10N

- Aerial Hazard
- Dip Site
- Helipad
- Sling Site
- Division Break
- Drop Point
- Camp
- Value at Risk
- Other
- Landmark
- Gate
- Bridge
- Structure Wrap
- Stream Crossing
- Resource Location
- Repair Point
- Hazard Tree
- Fence/Cut/Damaged
- Culvert
- Clean Up Area
- Mobile Weather Unit
- Repeater
- Road Repair
- Safety Zone
- Water Source
- Restricted Water Source
- Dozer Push
- Access or Improved Road
- Fence
- Repair Line
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- Completed - Inspected (46)
- Completed - Ready for Inspection (3)
- In Progress (11)
- Other - See Comments (3)
- Unknown (43)
- Completed - Inspected (491)
- Completed - Ready for Inspection (24)
- Roads
- Hazard
- Other - See Comments (22)
- Not Maintained
- Basic Custodial Care (CLOSED)
- OPEN
- Not Required (137)
- Other - See Comments (22)
- Unknown (17)
- Bureau of Land Management
- Forest Service
- Indian Reservation
- State
- Other - See Comments (3)
- Unknown (43)
- Completed - Inspected (491)
- Completed - Ready for Inspection (24)
- Roads
- Hazard
- Other - See Comments (22)
- Not Maintained
- Basic Custodial Care (CLOSED)
- OPEN
- Not Required (137)
- Other - See Comments (22)
- Unknown (17)
- Bureau of Land Management