



# Repair Status South Zone SE

## August Complex

### CA-MNF-000753

6/6/2021



0 0.5 1 2 Miles



Current as of: 6/6/2021  
NADECS UTM 21N



- |  |   |  |  |  |
|--|---|--|--|--|
| <ul style="list-style-type: none"> <li>● Dip Site</li> <li>● Helispot</li> <li>✕ Division Break</li> <li>■ Drop Point</li> <li>● Value at Risk</li> <li>● Other</li> <li>● Gate</li> <li>● Structure Wrap</li> <li>● Road Repair</li> <li>● Resource Location</li> </ul> | <ul style="list-style-type: none"> <li>● Repair Point</li> <li>● Hazard Tree</li> <li>● Fence - Cut/Damaged</li> <li>● Dozer Push</li> <li>● Culvert</li> <li>● Mobile Weather Unit</li> <li>● Repeater</li> <li>● Safety Zone</li> <li>● Hazard</li> <li>● Water Source</li> </ul> | <ul style="list-style-type: none"> <li>○ Restricted Water Source</li> <li>○ Completed Dozer Line</li> <li>○ Completed Hand Line</li> <li>○ Access or Improved Road</li> <li>○ Fence</li> <li>○ Other</li> <li>○ Road as Completed Line</li> <li>○ Completed - Inspected (87)</li> <li>○ Completed - Ready for Inspection (4)</li> <li>○ In Progress (5)</li> </ul> | <ul style="list-style-type: none"> <li>● Repair Needed (135)</li> <li>● No Repair Needed (22)</li> <li>● Other - See Comments (70)</li> <li>● Unknown (61)</li> <li>● Completed - Inspected (160)</li> <li>● Completed - Ready for Inspection (2)</li> <li>● In Progress (12)</li> <li>● Repair Needed (70)</li> <li>● No Repair Needed (60)</li> <li>● Other - See Comments (2)</li> <li>● Unknown (4)</li> </ul> | <ul style="list-style-type: none"> <li>● Bureau of Land Management</li> <li>● Forest Service</li> <li>● Indian Reservation</li> <li>● State</li> <li>● Road</li> <li>○ - 0 - Not Maintained</li> <li>○ - 1 - Basic Custodial Care (CLOSED)</li> <li>○ - 2 - 5 (OPEN)</li> <li>○ - Private or County</li> </ul> |
|--|---|--|--|--|