



**Need Repair South Zone SE**  
**August Complex**  
**CA-MNF-000753**  
**6/13/2021**



Current as of: 6/13/2021  
 NAD83 UTM 11N



- Dip Site
- Helipoint
- Division Break
- Drop Point
- Closure
- Value at Risk
- Other
- Landmark
- Gate
- Bridge
- Structure Wrap
- Stream Crossing
- Road Repair
- Resource Location
- Repair Point
- Hazard Trees
- Fence - Cut/Damaged
- Dozer Push
- Culvert
- Clean Up Area
- Mobile Weather Unit
- Repeater
- Safety Zone
- Hazard
- Water Source
- Restricted Water Source
- Completed Dozer Line
- Completed Hand Line
- Access or Improved Road
- Fence
- Repair Line
- Road Repair
- Road as Completed Line
- Completed - Inspected (13)
- Completed - Ready for Inspection (4)
- In Progress (5)
- Repair Needed (175)
- No Repair Needed (77)
- Other - See Comments (42)
- Unknown (151)
- Completed - Ready for Inspection (1)
- In Progress (18)
- Repair Needed (27)
- Other - See Comments (22)
- Unknown (7)
- Bureau of Land Management
- Forest Service
- State
- Roads
- - 0 - Not Maintained
- - 1 - Basic Custodial Care (CLOSED)
- - 2 - 5 (OPEN)
- Private or County