

Point Name	Feature	RepairStatus	Repair Comments	Lat	Long
95	Culvert	Repair Needed	culvert	40° 18.854'	-120° 38.115'
108	Culvert	Repair Needed	broken rotten culvert crossing for intermittent stream below road bed; likely still passes water	40° 17.308'	-120° 48.346'
36	Dozer Push	Repair Needed	Repair Point, Dozer Line And Push Pail In Seasonal Drainage	40° 17.580'	-120° 47.558'
97	Dozer Push	Repair Needed	Dozer Reopened road previously blocked with mound.	40° 21.939'	-120° 48.085'
98	Dozer Push	Repair Needed	Dozer filled armoured water crossing; no rolling dip, high diversion potential and stream capture by road bed	40° 21.934'	-120° 48.084'
99	Dozer Push	Repair Needed	Dozer impact; need to check out	40° 19.021'	-120° 38.414'
109	Dozer Push	Repair Needed	Dozer enhanced wide spot in road	40° 17.409'	-120° 48.570'
111	Dozer Push	Repair Needed	Dozer Junction; landing pile of wood, 1/2 old punkie moonlight trees, 1/2 freshly cut trees	40° 16.805'	-120° 48.630'
112	Dozer Push	Repair Needed	Dozer Push out on edge of riparian vegetation; moist soil observed at low point in center near single aspen tree, 150x100 ft.	40° 17.294'	-120° 48.755'
113	Dozer Push	Repair Needed	Dozer pushed Staging zone; 150x200 ft.	40° 17.319'	-120° 48.413'
119	Dozer Push	Repair Needed	Large push out Dozer Junction 200 ft wide	40° 16.065'	-120° 49.190'
133	Dozer Push	Repair Needed	Dozer Push Into Channel. Needs Excavator.	40° 15.954'	-120° 44.707'
135	Dozer Push	Repair Needed	Dozer Push	40° 17.218'	-120° 44.156'
136	Dozer Push	Repair Needed	Dozer Push	40° 17.173'	-120° 44.158'
137	Dozer Push	Repair Needed	Dozer Push	40° 16.559'	-120° 44.405'
138	Dozer Push	Repair Needed	Dozer Push	40° 16.133'	-120° 45.037'
140	Dozer Push	Repair Needed	Dozer push--needs repair--pull back berms	40° 17.785'	-120° 38.517'
40	Repair Point	Completed - Ins	berms and pushed over trees cat withrippers	40° 20.812'	-120° 42.862'
50	Repair Point	Completed - Ins	exc work	40° 20.997'	-120° 39.201'
51	Repair Point	Completed - Ins	excavator work on dzt line. mucked up creek	40° 20.915'	-120° 42.401'
141	Repair Point	Completed - Ins	Noxious weed site -- do not repair. Canada thistle	40° 17.539'	-120° 36.594'
37	Repair Point	Repair Needed	20ft hog fence 1 post	40° 20.954'	-120° 38.496'
38	Repair Point	Repair Needed	50' 4ft hog fence 4 tpost	40° 21.025'	-120° 38.359'
39	Repair Point	Repair Needed	be fence	40° 20.996'	-120° 38.297'
41	Repair Point	Repair Needed	bw	40° 21.521'	-120° 40.317'
42	Repair Point	Repair Needed	bw fence	40° 21.970'	-120° 41.752'
43	Repair Point	Repair Needed	bw fnce	40° 21.051'	-120° 38.626'
44	Repair Point	Repair Needed	bw fnce	40° 20.957'	-120° 38.692'
45	Repair Point	Repair Needed	d, zr dstry rd	40° 19.996'	-120° 39.327'
46	Repair Point	Repair Needed	debris in creek	40° 19.744'	-120° 40.224'
47	Repair Point	Repair Needed	dozer work on dozer line	40° 20.781'	-120° 42.569'
48	Repair Point	Repair Needed	dzt line to ne	40° 19.523'	-120° 40.103'
49	Repair Point	Repair Needed	ex cleanout ditch wp2	40° 21.736'	-120° 41.626'
52	Repair Point	Repair Needed	historic ditch filled	40° 19.839'	-120° 39.792'
53	Repair Point	Repair Needed	hog fnce posts 20	40° 20.977'	-120° 38.511'
54	Repair Point	Repair Needed	knock down berm	40° 21.604'	-120° 42.134'
55	Repair Point	Repair Needed	line goes across crk	40° 19.864'	-120° 39.928'
56	Repair Point	Repair Needed	minor creek, dzt can fix	40° 20.919'	-120° 38.380'
57	Repair Point	Repair Needed	minor debris in crk lime continues west	40° 19.976'	-120° 39.515'

Point Name	Feature	RepairStatus	Repair Comments	Lat	Long
58	Repair Point	Repair Needed	needs work	40° 21.217'	-120° 39.332'
59	Repair Point	Repair Needed	old wbarrd dzt line 2structures lost	40° 21.576'	-120° 43.801'
60	Repair Point	Repair Needed	really sandy line is really moguls	40° 20.285'	-120° 38.755'
61	Repair Point	Repair Needed	start	40° 21.072'	-120° 38.089'
62	Repair Point	Repair Needed	wp1 ex cleanout ditch	40° 21.809'	-120° 41.656'
63	Repair Point	Repair Needed	y	40° 19.382'	-120° 39.942'
64	Repair Point	Repair Needed	bw	40° 21.157'	-120° 36.035'
65	Repair Point	Repair Needed	A	40° 20.041'	-120° 37.054'
66	Repair Point	Repair Needed	A	40° 20.071'	-120° 36.940'
67	Repair Point	Repair Needed	ab	40° 20.579'	-120° 38.637'
68	Repair Point	Repair Needed	ab dzt rd, needs erosion contrl	40° 20.601'	-120° 38.279'
69	Repair Point	Repair Needed	bw	40° 21.271'	-120° 35.995'
70	Repair Point	Repair Needed	bw	40° 21.278'	-120° 35.972'
71	Repair Point	Repair Needed	bw	40° 21.289'	-120° 35.939'
72	Repair Point	Repair Needed	bw	40° 21.189'	-120° 35.799'
73	Repair Point	Repair Needed	bw	40° 21.447'	-120° 34.476'
74	Repair Point	Repair Needed	bw	40° 21.477'	-120° 34.405'
75	Repair Point	Repair Needed	bw	40° 21.505'	-120° 34.375'
76	Repair Point	Repair Needed	bw	40° 21.766'	-120° 35.797'
77	Repair Point	Repair Needed	bw	40° 21.789'	-120° 35.659'
78	Repair Point	Repair Needed	bw	40° 21.673'	-120° 35.823'
79	Repair Point	Repair Needed	bw	40° 21.684'	-120° 35.992'
80	Repair Point	Repair Needed	bw	40° 20.918'	-120° 36.932'
81	Repair Point	Repair Needed	bw	40° 21.264'	-120° 36.602'
82	Repair Point	Repair Needed	bw	40° 20.291'	-120° 36.621'
83	Repair Point	Repair Needed	bw and hog splice	40° 21.687'	-120° 36.059'
84	Repair Point	Repair Needed	bw fence	40° 21.205'	-120° 36.031'
85	Repair Point	Repair Needed	dzt line connects	40° 21.898'	-120° 35.410'
86	Repair Point	Repair Needed	field fc	40° 21.052'	-120° 37.215'
87	Repair Point	Repair Needed	gate post	40° 21.158'	-120° 36.047'
88	Repair Point	Repair Needed	ind action loader	40° 21.910'	-120° 35.155'
89	Repair Point	Repair Needed	skid work	40° 21.906'	-120° 35.454'
90	Repair Point	Repair Needed	xcavator work cteek xong	40° 20.912'	-120° 37.001'
91	Repair Point	Repair Needed	stream crossing	40° 16.164'	-120° 46.051'
92	Repair Point	Repair Needed	User created trail needs to be blocked prior to stream crossing	40° 21.918'	-120° 48.080'
96	Repair Point	Repair Needed	Doodle piles from Feller Buncher; skid everything over 10 inches; leave biomass and cull logs in place for cover over Dozer line	40° 20.302'	-120° 47.801'
100	Repair Point	Repair Needed	Feller buncher material below CP25	40° 20.316'	-120° 47.810'
101	Repair Point	Repair Needed	fish in pool stranded	40° 22.030'	-120° 48.157'
102	Repair Point	Repair Needed	good deck location where Dozer Line meets road; don't deck juniper	40° 20.473'	-120° 48.105'

Point Name	Feature	RepairStatus	Repair Comments	Lat	Long
103	Repair Point	Repair Needed	Placemark 7	40° 20.307'	-120° 47.805'
106	Repair Point	Repair Needed	Water bars below this point on dozer line	40° 20.441'	-120° 47.924'
107	Repair Point	Repair Needed	runs parallel to ephemeral stream 50 ft. upslope	40° 20.503'	-120° 48.438'
110	Repair Point	Repair Needed	Dozer filled ponding perennial channel from spring immediately above road; deep ruts , flowing water, no stream crossing	40° 17.328'	-120° 48.224'
114	Repair Point	Repair Needed	Feller bunched clumps along northern edge	40° 16.392'	-120° 49.153'
115	Repair Point	Repair Needed	Feller buncher bundles 20+; 1/2 merchantable	40° 17.420'	-120° 48.087'
116	Repair Point	Repair Needed	fuels for tracked chipper	40° 17.358'	-120° 48.166'
117	Repair Point	Repair Needed	increase in rock component of soil	40° 16.283'	-120° 49.211'
118	Repair Point	Repair Needed	intermittent channel filled with dirt, no drainage feature	40° 17.365'	-120° 48.683'
120	Repair Point	Repair Needed	Reopened closed road with no cross drains on streams; Dozer and vehicle tracks cross stream	40° 17.323'	-120° 48.720'
121	Repair Point	Repair Needed	sawn logs on north edge	40° 16.581'	-120° 49.006'
122	Repair Point	Repair Needed	Timber; a few scattered clumps of merchantable logs and scattered single logs	40° 17.013'	-120° 48.754'
123	Repair Point	Repair Needed	Timber; Large deck of logs, 1/2 - 3/4's merchantable	40° 17.157'	-120° 48.861'
124	Repair Point	Repair Needed	Timber on north edge of line; a feller bunched bundles, all trees cut at butt	40° 16.190'	-120° 49.205'
125	Repair Point	Repair Needed	Dozer cuts switchback--block ohv use	40° 21.051'	-120° 42.964'
126	Repair Point	Repair Needed	Interior dozer line, needs mapping	40° 19.921'	-120° 43.444'
127	Repair Point	Repair Needed	Interior dozer line, needs mapping	40° 20.143'	-120° 43.209'
130	Repair Point	Repair Needed	Special repair-- handline cuts through noxious weed patch (Canada thistle)	40° 18.658'	-120° 42.891'
131	Repair Point	Repair Needed	Spot fire (looks to be all cold black) outside fire perimeter. 3-5 acres	40° 19.124'	-120° 41.871'
132	Repair Point	Repair Needed	Needs archaeologist and hand crew	40° 15.311'	-120° 46.226'
135	Repair Point	Repair Needed	From Jake	40° 15.220'	-120° 45.246'
142	Repair Point	Repair Needed	Retardant drop in rare plant habitat. Not dozer line	40° 18.251'	-120° 39.439'
145	Repair Point	Repair Needed	Sensitive plants--need READ on site for repair	40° 18.540'	-120° 39.438'
25	Safety Zone	Repair Needed		40° 18.625'	-120° 39.392'
26	Safety Zone	Repair Needed		40° 18.613'	-120° 39.061'
128	Safety Zone	Repair Needed	Safety zone	40° 17.754'	-120° 43.676'
129	Safety Zone	Repair Needed	Safety zone -- needs repair	40° 18.479'	-120° 43.916'
143	Safety Zone	Repair Needed	Safety zone	40° 18.816'	-120° 39.043'
144	Safety Zone	Repair Needed	Safety zone--needs repair	40° 18.486'	-120° 39.003'
146	Staging Area	Repair Needed	Staging area--needs repair	40° 17.693'	-120° 38.527'
93	Stream Crossing	Repair Needed	crossing downstream for skidding	40° 20.492'	-120° 48.549'
94	Stream Crossing	Repair Needed	crossing for skidder	40° 20.348'	-120° 48.451'
104	Stream Crossing	Repair Needed	Reestablished stream channel captured by old road upstream of washout	40° 21.910'	-120° 48.069'
105	Stream Crossing	Repair Needed	stream abandoned man made diversion berm where culvert crossing was established prior to rock crossing and road closure berm	40° 21.908'	-120° 48.071'
134	Stream Crossing	Repair Needed	Stream Crossing	40° 15.862'	-120° 44.707'
139	Stream Crossing	Repair Needed	Dozer Crosses Stream Channel. Push Into Channel. Will Require An Excavator.	40° 16.155'	-120° 44.665'