



REPAIR/OPERATIONS

North Complex
 CA-PNF-001308
 10/18/2020
 South Branch- Page 1

- | | | | |
|--|---|--|---|
| <ul style="list-style-type: none"> • Aerial Hazard • Bridge • Culvert • Dip Site • Drop Point • Dozer Push • Fence - Cut/Damaged • Fire Station • Gate • Hazard • Hazard Tree • Helispot • Incident Command Post • Internet Access | <ul style="list-style-type: none"> • Landing or Log Deck • Lookout • Mobile Weather Unit • Repair Point • Repeater • Retardant in Avoidance Area • Safety Zone • Staging Area • Stream Crossing • Structure Wrap • Water Source • Water Development or Draft Site • Value at Risk • Other | <ul style="list-style-type: none"> 11 Division Break • SPI Gate • MANDATORY EXCLUSION AREA • MANDATORY EXCLUSION AREA • MANDATORY EXCLUSION AREA • Mine • Structure • SPI Fuelbreak • Contained Line • Completed Dozer Line • Completed Hand Line | <ul style="list-style-type: none"> • Road as Completed Line • Access or Improved Road • Completed PLOW Line • Aerial Retardant Drop • Repair Line • Road Repair • Event_Polygon • MANDATORY EXCLUSION AREA • cnty19_1_basic • Roads Open to All Vehicles, Yearlong • Roads Open to Highway Legal Vehicles Only, Yearlong |
|--|---|--|---|

Repair Status

- Completed - Inspection
- Completed - Ready for Inspection
- In Progress
- In Use - Fire Management
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

0 1 Miles
 1:26,000
 Map Updated: 10/17/2020 23:22