



Prepared by CRIMT12 9/19/2021 20:43

- | | | | |
|---|---|--|--|
| <ul style="list-style-type: none"> Pump Water Tank Aerial Hazard Check Point Dip Site Helibase Division Break Branch Break Camp Staging Area Other Gate | <ul style="list-style-type: none"> Structure Wrap Stream Crossing Road Repair Repair in Avoidance Area Repair Front Landing or Log Deck Hazard Tree Fence - Cut/Damaged Dozer Push Clean Up Area Mobile Weather Unit Repeater | <ul style="list-style-type: none"> Water Source Completed Dozer Line Completed Fuel Break Completed Hand Line Completed Mixed Construction Line Completed Road as Line Access or Improved Road Road Repair Retardant Drop Contained Line Completed - Inspected In Progress | <ul style="list-style-type: none"> Repair Needed Other - See Comments Unknown Completed - Inspected Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown Cleared ARCH Lines Cleared ARCH Lines |
|---|---|--|--|

SUPPRESSION REPAIR

Caldor

CA-ENF-24030

09/20/21



0 0.75 1.5 3 Miles
1:40,000 NAD83 UTM 11N

Caldor
CA-ENF-24030
REPAIR
Branch I
09/20/21