


<ul style="list-style-type: none"> ○ Check Point ○ Dip Site ○ Mobile Retardant Base ○ Helibase ○ Sling Site ○ Unimproved Landing Area ⊥ Division Break ⊥ Branch Break ⊥ Drop Point ⊥ Camp ⊥ Staging Area ⊥ Value at Risk 	<ul style="list-style-type: none"> ● Other ● Gate ● Bridge ● Water Development or Draft Site ● Stream Crossing ● Road Repair ● Retardant in Avoidance Area ● Resource Location ● Repair Point ● Landing or Log Deck ● Hazard Tree ● Fence - Cut/Damaged 	<ul style="list-style-type: none"> ◇ Dozer Push ◇ Clean Up Area ◇ Mobile Weather Unit ◇ Internet Access ◇ Repeater ◇ Retardant Dip ◇ Water Source ◇ Restricted Water Source ◇ Completed Dozer Line ◇ Completed Fuel Break ◇ Completed Hand Line ◇ Completed Mixed Construction Line 	<ul style="list-style-type: none"> - Completed Road as Line - Planned Hand Line - Access or Improved Road - Repair Line - Road Repair - Retardant Dip - Fire Edge - Contained Line - Completed - Inspected - In Use - Fire Management - Completed Hand Line - Completed Mixed Construction Line 	<ul style="list-style-type: none"> ○ Repair Needed ○ No Repair Needed ○ Other - See Comments ○ Unknown ○ Completed - Inspected ○ Completed - Ready for Inspection ○ In Progress ○ Repair Needed ○ No Repair Needed ○ Other - See Comments ○ Unknown ○ In Progress
--	---	---	---	---

SUPPRESSION REPAIR

Caldor

CA-ENF-24030

09/28/21



Caldor
CA-ENF-24030
REPAIR
Branch III
09/28/21