



# SUPPRESSION REPAIR

**Caldor**

CA-ENF-24030

October 2, 2021



- |   |   |  |
|---|---|--|
| <ul style="list-style-type: none"> <li> Aerial Hazard</li> <li> Check Point</li> <li> Dip Site</li> <li> Helibase</li> <li> Division Break</li> <li> Branch Break</li> <li> Drop Point</li> <li> Camp</li> <li> Staging Area</li> <li> Other</li> <li> Gate</li> <li> Structure Wrap</li> <li> Stream Crossing</li> </ul> | <ul style="list-style-type: none"> <li> Road Repair</li> <li> Retardant in Avoidance Area</li> <li> Repair Point</li> <li> Landing or Log Deck</li> <li> Hazard Tree</li> <li> Fence - Cut/Damaged</li> <li> Dozer Push</li> <li> Clean Up Area</li> <li> Mobile Weather Unit</li> <li> Internet Access</li> <li> Repeater</li> <li> Water Source</li> <li> Completed Dozer Line</li> </ul> | <ul style="list-style-type: none"> <li> Completed Fuel Break</li> <li> Completed Hand Line</li> <li> Completed Mixed Construction Line</li> <li> Completed Road as Line</li> <li> Access or Improved Road</li> <li> Retardant Drop</li> <li> Contained Line</li> <li> Wildfire Daily Fire Perimeter</li> <li> Completed - Inspected</li> <li> Completed - Ready for Inspection</li> <li> In Progress</li> <li> Repair Needed</li> <li> No Repair Needed</li> <li> Other - See Comments</li> <li> Unknown</li> <li> Cleared ARCH Lines</li> <li> Cleared ARCH Lines</li> <li> Retardant Arch Line</li> <li> Other - See Comments</li> </ul> |
|---|---|--|



Interagency Incident Management  
 0 0.75 1.5 3 Miles  
 1:40,000 NAD83 UTM 11N

**REPAIR**  
 Branch I  
 Caldor  
 CA-ENF-24030