


<ul style="list-style-type: none"> ● Aerial Hazard ● Check Point ● Dip Site ● Mobile Retardant Base ● Helibase ● Sling Site ● Unimproved Landing Area X Division Break ● Branch Break ● Drop Point ● Camp ● Staging Area ● Value at Risk ● Other ● Gate ● Bridge ● Water Development or Draft Site 	<ul style="list-style-type: none"> ● Structure Wrap ● Stream Crossing ● Road Repair ● Retardant in Avoidance Area ● Resource Location ● Repair Rate ● Landing or Log Deck ● Hazard Tree ● Fence - Cut/Damaged ● Down Path ● Clean Up Area ● Mobile Weather Unit ● Internet Access ● Repairer ● Hazard ● Water Source ● Restricted Water Source 	<ul style="list-style-type: none"> M Completed Dozer Line M Completed Fuel Break M Completed Hand Line M Completed Mixed Construction Line M Flamed Hand Line Access or Improved Road Repair Line Road Repair Retardant Drop Fire Edge Completed - Inspected In Use - Fire Management Completed - Ready for Inspection 	<ul style="list-style-type: none"> ● In Progress ● No Repair Needed ● Other - See Comments ● Unknown ● Completed - Ready for Inspection ● In Progress ● Repair Needed ● No Repair Needed ● Other - See Comments ● Unknown
---	---	---	---

SUPPRESSION REPAIR

Caldor

CA-ENF-24030
October 4, 2021



REPAIR Overview
Caldor
CA-ENF-24030

