



Event Point	Bridge	Hazard	Fire Edge	No Repair Needed
Aerial Hazard	Water Development or Draft Site	Water Source	Contained Line	Other - See Comments
Check Point	Structure Wires	Restrictive Water Source	Repair Status Line	Unknown
Dip Point	Stream Crossing	Event Line	Completed - Inspected	California Wildland Fire Direct Protection Areas - 2021
Mobile Retardant Base	Road Repair	Completed Dozer Line	FEDERAL	In Use - Fire Management
Helibase	Retardant in Avoidance Area	Completed Fuel Break	STATE	Completed - Ready for Inspection
Sling Site	Resource Location	Completed Hand Line	LOCAL	In Progress
Unimproved Landing Area	Repair Point	Completed Mixed Construction Line	Report Area Completion %	Repair Needed
Division Break	Landing or Log Deck	Completed Road as Line	1 - 25	No Repair Needed
Branch Break	Hazard Tree	Planned Hand Line	26 - 50	Other - See Comments
Drop Point	Fence - Cut/Damaged	Access or Improved Road	51 - 75	Unknown
Camp	Dozer Push	Repair Line	76 - 100	Repair Status Line
Staging Area	Clean Up Area	Road Repair	Completed - Inspected	Completed - Ready for Inspection
Walk at Risk	Mobile Weather Unit	Internet Access	In Progress	Repair Needed
Other	Retardant Drop	Route		
Gate	Repeater			

SUPPRESSION REPAIR REPORTING AREAS

Caldor

CA-ENF-24030
October 5, 2021



0 1.5 3 6 Miles
1:78,000 NAD83 UTM 11N

REPAIR REPORT
Caldor
CA-ENF-24030