



SUPPRESSION REPAIR

Caldor

CA-ENF-24030
October 6, 2021



- | | | | | |
|--|---|---|---|--|
| <ul style="list-style-type: none"> ⊙ Aerial Hazard ⊙ Check Point ⊙ Dip Site ⊙ Mobile Retardant Base ⊙ Helibase ⊙ Sling Site ⊙ Unimproved Landing Area ⊙ Division Break ⊙ Branch Break ⊙ Drop Point ⊙ Camp ⊙ Staging Area ⊙ Value at Risk ⊙ Other | <ul style="list-style-type: none"> ⊙ Gate ⊙ Bridge ⊙ Water Development or Draft Site ⊙ Structure Wrap ⊙ Stream Crossing ⊙ Road Repair ⊙ Retardant in Avoidance Area ⊙ Resource Location ⊙ Repair Point ⊙ Landing or Log Deck ⊙ Hazard Tree ⊙ Fence - Cut/Damaged ⊙ Dozer Push ⊙ Clean Up Area | <ul style="list-style-type: none"> ⊙ Mobile Weather Unit ⊙ Internet Access ⊙ Repeater ⊙ Hazard ⊙ Water Source ⊙ Restricted Water Source ⊙ Completed Fuel Line ⊙ Completed Hand Line ⊙ Completed Mixed Construction Line ⊙ Completed Road as Line ⊙ Planned Hand Line ⊙ Access or Improved Road ⊙ Other | <ul style="list-style-type: none"> — Repair Line — Road Repair — Retardant Drop — Route — Fire Edge — Contained Line — Completed - Inspected — Completed - In Progress — In Use - Fire Management — Completed - Ready for Inspection — In Progress — Repair Needed — No Repair Needed — Other - See Comments — Unknown | <ul style="list-style-type: none"> — Completed - Inspected — Completed - Ready for Inspection — In Progress — Repair Needed — No Repair Needed — Other - See Comments — Unknown |
|--|---|---|---|--|



REPAIR OVERVIEW
Caldor
CA-ENF-24030

0 1.5 3 6 Miles
1:78,000 NAD83 UTM 11N