



Event Point	Bridge	Hazard	Fire Edge	No Repair Needed
Aerial Hazard	Water Development or Draft Site	Water Source	Contained Line	Other - See Comments
Check Point	Structure Wires	Restrictive Water Source	Repair Status Line	Unknown
Dip Point	Stream Crossing	Event Line	Completed - Inspected	California Wildland Fire Direct Protection Areas - 2021
Mobile Retardant Base	Road Repair	Completed Dozer Line	In Use - Fire Management	FEDERAL
Helibase	Retardant in Avoidance Area	Completed Fuel Break	Completed - Ready for Inspection	STATE
Sling Site	Resource Location	Completed Hand Line	In Progress	LOCAL
Unimproved Landing Area	Repair Point	Completed Mixed Construction Line	Repair Needed	Report Area Completion %
Division Break	Landing or Log Deck	Completed Road as Line	No Repair Needed	0
Branch Break	Hazard Tree	Planned Hand Line	Other - See Comments	1 - 25
Drop Point	Fence - Cut/Damaged	Access or Improved Road	Unknown	26 - 50
Camp	Dozer Push	Repair Line	Repair Status Line	51 - 75
Staging Area	Clean Up Area	Road Repair	Completed - Inspected	76 - 100
Walk at Risk	Mobile Weather Unit	Completed - Ready for Inspection	In Progress	Roads - N South, Hornon Emigrant, Silver Fork
Other	Internet Access	Retardant Drop	Repair Needed	
Gate	Repeater	Route		

**SUPPRESSION REPAIR
REPORTING AREAS**
Caldor
CA-ENF-24030
October 7, 2021



0 1.5 3 6 Miles
1:78,000 NAD83 UTM 11N

**REPAIR
REPORT**
Caldor
CA-ENF-24030