


Prepared by: CAIMT13 10/8/2021 20:51

<ul style="list-style-type: none"> Aerial Hazard Check Point Dip Site Helibase Sling Site Unimproved Landing Area Division Break Branch Break Drop Point Camp Staging Area Lookout Value at Risk Other 	<ul style="list-style-type: none"> Gate Water Development or Draft Site Stream Crossing Road Repair Retardant in Avoidance Area Resource Location Repair Point Landing or Log Deck Hazard Tree Fence - Cut/Damaged Dozer Push Clean Up Area Mobile Weather Unit 	<ul style="list-style-type: none"> Internet Access Repeater Hazard Water Source Restricted Water Source Completed Dozer Line Completed Fuel Break Completed Hand Line Completed Mixed Construction Line Planned Hand Line Access or Improved Road Other Repair Line 	<ul style="list-style-type: none"> Road Repair Retardant Drop Route Fire Edge Contained Line Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown Completed - Inspected 	<ul style="list-style-type: none"> Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown Completed - Inspected
--	--	--	--	--

SUPPRESSION REPAIR

Caldor

CA-ENF-24030
October 9, 2021



REPAIR
Branch III
Caldor
October 9, 2021
CA-ENF-24030