


<ul style="list-style-type: none"> <li>Aerial Hazard</li> <li>Check Point</li> <li>Dip Site</li> <li>Helibase</li> <li>Slings</li> <li>Unimproved Landing Area</li> <li>Division Break</li> <li>Drop Point</li> <li>Camp</li> <li>Staging Area</li> <li>Lookout</li> <li>Value at Risk</li> <li>Other</li> <li>Gate</li> </ul>	<ul style="list-style-type: none"> <li>Bridge</li> <li>Water Development or Draft Site</li> <li>Stream Crossing</li> <li>Road Repair</li> <li>Retardant in Avoidance Area</li> <li>Resource Location</li> <li>Repair Point</li> <li>Hazard Tree</li> <li>Fence - Cut/Damaged</li> <li>Dozer Push</li> <li>Clean Up Area</li> <li>Mobile Weather Unit</li> <li>Internet Access</li> <li>Repeater</li> </ul>	<ul style="list-style-type: none"> <li>Hazard</li> <li>Restricted Water Source</li> <li>Completed Dozer Break</li> <li>Completed Hand Line</li> <li>Completed Mixed Construction Line</li> <li>Completed Road as Line</li> <li>Planned Hand Line</li> <li>Access or Improved Road</li> <li>Repair Line</li> <li>Road Repair</li> <li>Retardant Drop</li> <li>Route</li> </ul>	<ul style="list-style-type: none"> <li>Fire Edge</li> <li>Contained Line</li> <li>Completed - Inspected</li> <li>In Use - Fire Management</li> <li>Completed - Ready for Inspection</li> <li>In Progress</li> <li>Repair Needed</li> <li>No Repair Needed</li> <li>Other - See Comments</li> <li>Unknown</li> <li>Completed - Ready for Inspection</li> <li>In Progress</li> <li>Repair Needed</li> </ul>	<ul style="list-style-type: none"> <li>No Repair Needed</li> <li>Other - See Comments</li> <li>Unknown</li> <li>California Wildland Fire Direct Protection Areas - 2021</li> <li>FEDERAL</li> <li>STATE</li> <li>LOCAL</li> <li>Secondary Fuel Breaks</li> <li>Haz/Tree Priority/Roads</li> <li>Primary Fuel Breaks</li> </ul>
--	--	---	---	--

# SUPPRESSION REPAIR

## Caldor

CA-ENF-24030  
October 9, 2021



**REPAIR**  
**DIV O, P, Q**  
**Caldor**  
**CA-ENF-24030**

© 2021 NASA, NGA, USGS, FEMA