


<ul style="list-style-type: none"> Aerial Hazard Check Point Dip Site Helibase Sling Site Unimproved Landing Area Division Break Branch Break Drop Point Camp Sloping Area Lookout Value at Risk Other Gate Bridge Water Development or Draft Site 	<ul style="list-style-type: none"> Stream Crossing Road Repair Retardant in Avoidance Area Resource Location Repair Point Landing or Log Deck Hazard Tree Fence - Cut/Damaged Dozer Push Clean Up Area Mobile Weather Unit Internet Access Repeater Hazard Water Source Quarantined Water Source Completed Dozer Line 	<ul style="list-style-type: none"> Completed Fuel Break Completed Hand Line Completed Mixed Construction Line Completed Road as Line Planned Hand Line Access or Improved Road Other Repair Line Road Repair Retardant Drop Mobile Weather Unit Fire Edge Contained Line US - US Route SR - State Route FC - Functionally Classified Other System EN/Road TM/Road HT/Road Trail In Use - Fire Management Completed - Inspected Completed - Ready for Inspection In Progress No Repair Needed Other - See Comments Unknown S1640 S1710 S1740 S1750 S1100 S1200 S1400 S1500 	<ul style="list-style-type: none"> Other - See Comments Unknown Completed - Inspected Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown California Wildland Fire Direct Protection Areas - 2021 FEDERAL STATE LOCAL Secondary Fuel Breaks Haz/Tree Priority/Roads Primary Fuel Breaks
---	--	--	--

SUPPRESSION REPAIR

Caldor

CA-ENF-24030
October 10, 2021



REPAIR
Branch III
Caldor
October 10, 2021
CA-ENF-24030