



Prepared by: CAIMT13 10/9/2021 21:19

- | | | | |
|--|--|---|---|
| <ul style="list-style-type: none"> ● Aerial Hazard ○ Check Point ○ Dip Site ○ Helibase ○ Staging Area ○ Unimproved Landing Area X Division Break II Branch Break ○ Drop Point ○ Staging Area ○ Lookout ○ Value at Risk ○ Other ○ Bridge ○ Water Development or Draft Site ○ Structure Wrap | <ul style="list-style-type: none"> ● Stream Crossing ● Road Repair ● Retardant in Avoidance Area ● Resource Location ● Staging Area ● Hazard Tree ● Fence - Cut/Damaged ● Dropper Path ● Clean Up Area ● Mobile Weather Unit ● Internet Access ● Values at Risk ● Other ● Water Source ● Restricted Water Source ● Water Development or Draft Site ● Structure Wrap | <ul style="list-style-type: none"> H - Completed Hand Line M - Completed Hand Construction Line R - Completed Road as Line SR - State Route RM - Ramp AR - Access Route PC - Functionally Classified Other System ENFRoad THURoad HTFRoad Trail Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments | <ul style="list-style-type: none"> ○ Unknown ● Completed - Inspected ● Completed - Ready for Inspection ● In Progress ● Repair Needed ● No Repair Needed ● Other - See Comments Unknown STATE LOCAL Secondary Fuel Breaks HeadTree PriorityRoads Primary Fuel Breaks |
|--|--|---|---|

SUPPRESSION REPAIR

Caldor

CA-ENF-24030
October 10, 2021



Interagency Incident Management
0 1.5 3 6 Miles
1:78,000 NAD83 UTM 11N

REPAIR OVERVIEW
Caldor
October 10, 2021
CA-ENF-24030