



Event Point	Road Repair	Completed Hand Line	Repair Status Line
Aerial Hazard	Retardant in Avoidance Area	Completed Mixed Construction Line	Completed - Inspected
Check Point	Repair Point	Completed Road as Line	Completed - Ready for Inspection
Dip Site	Landing or Log Deck	Access or Improved Road	In Progress
Hillbase	Hazard Tree	Road Repair	Repair Needed
Division Break	Fence - Cut/Damaged	Retardant Drop	No Repair Needed
Branch Break	Dozer Push	Contained Line	Other - See Comments
Drop Point	Clean Up Area	Trail	Unknown
Camp	Mobile Weather Unit	California Wildland Fire Direct Protection Areas - 2021	FEDERAL
Staging Area	Internet Access	Repair Status Point	STATE
Value at Risk	Water Source	Completed - Inspected	LOCAL
Gate	Event Line	Repair Needed	No Repair Needed
Structure Wrap	Completed Dozer Line	Other - See Comments	Secondary Fuel Breaks
Stream Crossing	Completed Fuel Break	Unknown	Haz/Tree Priority Roads
			Primary Fuel Breaks

SUPPRESSION REPAIR

Caldor
 CA-ENF-24030
 October 11, 2021



0 0.75 1.5 3 Miles
 1:40,000 NAD83 UTM 11N

REPAIR
 Branch I
 Caldor
 October 11, 2021
 CA-ENF-24030