

Branch I

Div G

Div D

Div A

Div W

Div T


# SUPPRESSION REPAIR

Caldor  
CA-ENF-24030

October 11, 2021



- |   |  |   |  |
|---|--|---|--|
| <ul style="list-style-type: none"> <li>Event Point</li> <li>Aerial Hazard</li> <li>Check Point</li> <li>Dip Site</li> <li>Helibase</li> <li>Division Break</li> <li>Branch Break</li> <li>Drop Point</li> <li>Camp</li> <li>Staging Area</li> <li>Value at Risk</li> <li>Water Source</li> <li>Gate</li> <li>Structure Wrap</li> <li>Stream Crossing</li> </ul> | <ul style="list-style-type: none"> <li>Road Repair</li> <li>Retardant in Avoidance Area</li> <li>Repair Point</li> <li>Landing or Log Deck</li> <li>Hazard Tree</li> <li>Fence - Cut/Damaged</li> <li>Dozer Push</li> <li>Clean Up Area</li> <li>Mobile Weather Unit</li> <li>Internet Access</li> <li>Responder</li> <li>Other</li> <li>Event Line</li> <li>Completed Dozer Line</li> <li>Completed Fuel Break</li> </ul> | <ul style="list-style-type: none"> <li>Completed Hand Line</li> <li>Completed Mixed Construction Line</li> <li>Completed Road as Line</li> <li>Access or Improved Road</li> <li>Road Repair</li> <li>Retardant Drop</li> <li>Contained Line</li> <li>Trail</li> <li>Repair Status Point</li> <li>Completed - Inspected</li> <li>Repair Needed</li> <li>No Repair Needed</li> <li>Other - See Comments</li> <li>Unknown</li> </ul> | <ul style="list-style-type: none"> <li>Repair Status Line</li> <li>Completed - Inspected</li> <li>Completed - Ready for Inspection</li> <li>In Progress</li> <li>Repair Needed</li> <li>No Repair Needed</li> <li>Other - See Comments</li> <li>Unknown</li> <li>California Wildland Fire Direct Protection Areas - 2021</li> <li>FEDERAL</li> <li>STATE</li> <li>LOCAL</li> <li>Secondary Fuel Breaks</li> <li>HazTree Priority Roads</li> <li>Primary Fuel Breaks</li> </ul> |
|---|--|---|--|



REPAIR  
Branch I  
Caldor  
October 11, 2021  
CA-ENF-24030

0 0.75 1.5 3 Miles  
1:40,000 NAD83 UTM 11N

Prepared by: CAIIMT13 10/10/2021 20:32