



SUPPRESSION REPAIR

Caldor
 CA-ENF-24030
 October 11, 2021

Prepared by: CAIIMT13 10/10/2021 20:49

- Aerial Hazard
- Check Point
- Dip Site
- Helibase
- Unimproved Landing Area
- Division Break
- Branch Break
- Drop Point
- Staging Area
- Lookout
- Value at Risk
- Other
- Bridge
- Water Development or Draft Site
- Structure Wrap
- Stream Crossing
- Road Repair
- Retardant in Avoidance Area
- Resource Location
- Slings
- Landing or Log Check
- Hazard Tree
- Fence - Cut/Damaged
- Dropper Pulp
- Clean Up Area
- Mobile Weather Unit
- Internet Access
- Other at Risk
- Hazard
- Water Source
- Restricted Water Source
- Completed Outer Line
- Completed Full Break
- Completed Hand Line
- Completed Hand Construction Line
- US - US Route
- SR - State Route
- RV - Ramp
- AR - Access Route
- PC - Functionally Classified Other System
- ENFRoad
- THRoad
- HTRoad
- Trail
- Completed - Inspected
- In Use - Fire Management
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown
- California Wildland Fire Direct Protection Area - 2021
- STATE
- LOCAL
- Secondary Fuel Breaks
- Hot Tree Priority Roads
- Primary Fuel Breaks



REPAIR OVERVIEW
 Caldor
 October 11, 2021
 CA-ENF-24030

