



Meyer Repair Area - Echo

Caldor
 CA-ENF-24030
 October 12, 2021



<ul style="list-style-type: none"> Other Property Pump Water Tank Wellhead Sling Site Drop Point Cache Staging Area Lookout 	<ul style="list-style-type: none"> Road Repair Fence - Cut/Damaged Clear Up Area Mobile Weather Unit Repeater Handset Water Source Completed Dezer Line Completed Fuel Break Completed Hand Line Completed Mixed Construction Line Completed Road as Line Planned Road Line Road Line Road Repair Road Water Source Completed Dezer Line 	<ul style="list-style-type: none"> Forest Service Land State Public Lands Other State Lands Private, Local Government, Undesignated Primary Fuel Breaks Secondary Fuel Breaks HazTree Priority Roads Repair Status Accountable Property Completed - Inspected 	<ul style="list-style-type: none"> In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown 	<ul style="list-style-type: none"> Repair Status Point Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown 	<ul style="list-style-type: none"> Repair Status Line Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown
--	--	--	---	---	--