


# Meyer Repair Area - Echo

Caldor  
 CA-ENF-24030  
 October 12, 2021



<ul style="list-style-type: none"> <li>Other Property</li> <li>Pump</li> <li>Water Tank</li> <li>Water Push</li> <li>Slings</li> <li>Division Break</li> <li>Drop Point</li> <li>Head</li> <li>Camp</li> <li>Staging Area</li> <li>Lookout</li> </ul>	<ul style="list-style-type: none"> <li>Road Repair</li> <li>Fence - Cut/Damaged</li> <li>Clear Push</li> <li>Slings</li> <li>Mobile Weather Unit</li> <li>Repeater</li> <li>Head</li> <li>Water Source</li> <li>Staging Area</li> <li>Completed Dozer Line</li> </ul>	<ul style="list-style-type: none"> <li>Completed Fuel Break</li> <li>Completed Mixed Construction Line</li> <li>Completed Road as Line</li> <li>Flamed Road Line</li> <li>Repair Line</li> <li>Road Repair</li> <li>Road</li> <li>Water Source</li> <li>Completed Dozer Line</li> </ul>	<ul style="list-style-type: none"> <li>Forest Service Land</li> <li>State Public Lands</li> <li>Other State Lands</li> <li>Private, Local Government, Undesignated</li> <li>Primary Fuel Breaks</li> <li>Secondary Fuel Breaks</li> <li>HazTree Priority Roads</li> </ul>	<ul style="list-style-type: none"> <li>In Use - Fire Management</li> <li>Completed - Ready for Inspection</li> <li>In Progress</li> <li>Repair Needed</li> <li>No Repair Needed</li> <li>Other - See Comments</li> <li>Unknown</li> </ul>	<ul style="list-style-type: none"> <li>Repair Status Point</li> <li>Completed - Inspected</li> <li>In Use - Fire Management</li> <li>Completed - Ready for Inspection</li> <li>In Progress</li> <li>Repair Needed</li> <li>No Repair Needed</li> <li>Other - See Comments</li> <li>Unknown</li> </ul>	<ul style="list-style-type: none"> <li>Repair Status Line</li> <li>Completed - Inspected</li> <li>In Use - Fire Management</li> <li>Completed - Ready for Inspection</li> <li>In Progress</li> <li>Repair Needed</li> <li>No Repair Needed</li> <li>Other - See Comments</li> <li>Unknown</li> </ul>
---	---	---	---	---	---	--