


Meyer Repair Area - Fallen Leaf

Caldor
 CA-ENF-24030
 October 12, 2021



- | | | | | | |
|--|---|--|--|---|--|
| <ul style="list-style-type: none"> Check Point Road Repair Repair Point Landing or Log Deck Fence - Cut/Damaged Dozer Push Restricted Water Source Completed Dozer Line Completed Fuel Break Completed Hand Line | <ul style="list-style-type: none"> R Completed Road as Line H Planned Hand Line Road Repair Forest Service Land State Public Lands Other State Lands Primary Fuel Breaks Secondary Fuel Breaks HazTree Priority Roads | <ul style="list-style-type: none"> Repair Status Accountable Property Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed | <ul style="list-style-type: none"> Repair Status Point Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress | <ul style="list-style-type: none"> Repair Status Line Completed - Inspected In Use - Fire Management Completed - Ready for Inspection | <ul style="list-style-type: none"> Repair Needed No Repair Needed Other - See Comments Unknown |
|--|---|--|--|---|--|



1:18,000
 NAD83 UTM 11N
 Prepared by: GB Team 7 10/11/2021 20:27