









<ul style="list-style-type: none"> Other Property Pump Water Tank Dip Site Helispot Sling Site Division Break Drop Point Camp Lookout 	<ul style="list-style-type: none"> Road Repair Repair Point Landing or Log Deck Fence - Cut/Damaged Dozer Push Clean Up Area Fire Edge Wildfire Daily Fire Perimeter Forest Service Land Completed Dozer Line Completed Hand Line 	<ul style="list-style-type: none"> Completed Mixed Construction Line Completed Road as Line Planned Hand Line Other Road Repair Contained Line Wildfire Daily Fire Perimeter Forest Service Land Primary Fuel Breaks 	<ul style="list-style-type: none"> Secondary Fuel Breaks HazTree Priority Roads <p>Repair Status Accountable Property</p> <ul style="list-style-type: none"> Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed
---	---	--	---

Meyer Repair Area - Little Round Top

Caldor
CA-ENF-24030
October 12, 2021

