


- Check Point
 - Road Repair
 - Repair Point
 - Landing or Log Deck
 - Fence - Cut/Damaged
 - Dozer Push
 - Restricted Water Source
 - Completed Dozer Line
 - Completed Fuel Break
 - Completed Hand Line
 - Completed Road as Line
 - Planned Hand Line
 - Road Repair
 - Forest Service Land
 - State Public Lands
 - Other State Lands
 - Primary Fuel Breaks
 - Secondary Fuel Breaks
- Repair Status Accountable Property**
- Completed - Inspected
 - In Use - Fire Management
 - Completed - Ready for Inspection
 - In Progress
 - Repair Needed
 - No Repair Needed
 - Other - See Comments
 - Unknown
- Repair Status Line**
- Completed - Inspected
 - In Use - Fire Management
 - Completed - Ready for Inspection
 - In Progress
 - Repair Needed
 - No Repair Needed
 - Other - See Comments
 - Unknown
- Repair Status Point**
- Completed - Inspected
 - In Use - Fire Management

Meyer Repair Area - Fallen Leaf

Caldor
 CA-ENF-24030
 October 13, 2021



0 0.35 0.7 1.4 Miles

1:18,000

NAD83 UTM 11N
 Prepared by: GB Team 7 10/12/2021 20:05