


<ul style="list-style-type: none"> Aerial Hazard Check Point Dip Site Hillbase Slingside Unimproved Landing Area Division Break Drop Point Staging Area Clean Up Area Mobile Weather Unit Internet Access Other Gate Bridge Water Development or Draft Site 	<ul style="list-style-type: none"> Stream Crossing Road Repair Retardant in Avoidance Area Resource Location Repair Point Hazard Tree Fence - Cut/Damaged Door Push Clean Up Area Mobile Weather Unit Internet Access Repeater Hazard Water Source Restricted Water Source 	<ul style="list-style-type: none"> Completed Doser Line Completed Fuel Break Completed Hand Line Completed Mixed Construction Line Completed Road as Line Planned Hand Line Access or Improved Road Repair Line Road Repair Retardant Drop Route Fire Edge Contained Line S1200 S1400 	<ul style="list-style-type: none"> S1500 S1710 S1740 S1750 DNFRoad TRSRoad HTFRoad Trail In Use - Fire Management In Progress Repair Needed No Repair Needed Other - See Comments Unknown 	<ul style="list-style-type: none"> Completed - Inspected In Progress Repair Needed No Repair Needed Other - See Comments Unknown
---	---	--	---	--

SUPPRESSION REPAIR

Caldor

CA-ENF-24030
October 13, 2021



0 0.38 0.75 1.5 Miles
1:23,500 NAD83 UTM 11N

REPAIR
DIV O, P, Q
Caldor
CA-ENF-24030
October 13, 2021

Prepared by: GB Team 7 10/12/2021 20:38