



<ul style="list-style-type: none"> ■ Drop Point Completed Dozer Line Forest Service Land Primary Fuel Breaks Secondary Fuel Breaks HazTree Priority Roads 	<ul style="list-style-type: none"> Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown 	<p>Repair Status Point</p> <ul style="list-style-type: none"> Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments 	<p>Repair Status Line</p> <ul style="list-style-type: none"> Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown
<p>Repair Status Accountable Property</p> <ul style="list-style-type: none"> Completed - Inspected In Use - Fire Management 			

Meyer Repair Area - DP72 Road Work

Caldor
CA-ENF-24030
October 14, 2021

