



- |  |   |   |
|--|---|---|
| <ul style="list-style-type: none"> <li> Check Point</li> <li> Road Repair</li> <li> Repair Point</li> <li> Landing or Log Deck</li> <li> Fence - Cut/Damaged</li> <li> Dozer Push</li> <li> Restricted Water Source</li> <li> Completed Dozer Line</li> <li> Completed Fuel Break</li> <li> Completed Hand Line</li> <li> Completed Road as Line</li> <li> Planned Hand Line</li> <li> Road Repair</li> <li> Forest Service Land</li> <li> State Public Lands</li> <li> Other State Lands</li> <li> Primary Fuel Breaks</li> <li> Secondary Fuel Breaks</li> </ul> | <ul style="list-style-type: none"> <li> HazTree Priority Roads</li> </ul> <p><b>Repair Status Accountable Property</b></p> <ul style="list-style-type: none"> <li> Completed - Inspected</li> <li> In Use - Fire Management</li> <li> Completed - Ready for Inspection</li> <li> In Progress</li> <li> Repair Needed</li> <li> No Repair Needed</li> <li> Other - See Comments</li> <li> Unknown</li> </ul> <p><b>Repair Status Line</b></p> <ul style="list-style-type: none"> <li> Completed - Inspected</li> <li> In Use - Fire Management</li> <li> Completed - Ready for Inspection</li> <li> In Progress</li> <li> Repair Needed</li> <li> No Repair Needed</li> <li> Other - See Comments</li> <li> Unknown</li> </ul> <p><b>Repair Status Point</b></p> <ul style="list-style-type: none"> <li> Completed - Inspected</li> <li> In Use - Fire Management</li> </ul> | <ul style="list-style-type: none"> <li> Completed - Ready for Inspection</li> <li> In Progress</li> <li> Repair Needed</li> <li> No Repair Needed</li> <li> Other - See Comments</li> <li> Unknown</li> </ul> |
|--|---|---|

# Meyer Repair Area - Fallen Leaf

Caldor  
CA-ENF-24030  
October 14, 2021



1:18,000

NAD83 UTM 11N  
Prepared by: GB Team 7 10/13/2021 20:15