





- | | | |
|---|--|--|
| <ul style="list-style-type: none"> Other Property Pump Water Tank Dip Site Helispot Sling Site Drop Point Lookout Road Repair Repair Point Landing or Log Deck Fence - Cut/Damaged Dozer Push Clean Up Area Repeater Hazard Completed Dozer Line Completed Hand Line Completed Mixed Construction Line Completed Road as Line Planned Hand Line Other | <ul style="list-style-type: none"> Road Repair Fire Edge Contained Line Wildfire Daily Fire Perimeter Forest Service Land Primary Fuel Breaks Secondary Fuel Breaks HazTree Priority Roads | <p>Repair Status Point</p> <ul style="list-style-type: none"> Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown <p>Repair Status Accountable Property</p> <ul style="list-style-type: none"> Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown <p>Repair Status Line</p> <ul style="list-style-type: none"> Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown |
|---|--|--|

Meyer Repair Area - Little Round Top

Caldor
CA-ENF-24030
October 14, 2021



1:24,000
NAD83 UTM 11N
Prepared by: GB Team 7 10/13/2021 20:15