


- Check Point
  - Road Repair
  - Repair Point
  - Landing or Log Deck
  - Fence - Cut/Damaged
  - Dozer Push
  - Restricted Water Source
  - Completed Dozer Line
  - Completed Fuel Break
  - Completed Hand Line
  - Completed Road as Line
  - Planned Hand Line
  - Road Repair
  - Forest Service Land
  - State Public Lands
  - Other State Lands
  - Primary Fuel Breaks
  - Secondary Fuel Breaks
- HazTree Priority Roads**
- Repair Status Accountable Property
  - Completed - Inspected
  - In Use - Fire Management
  - Completed - Ready for Inspection
  - In Progress
  - Repair Needed
  - No Repair Needed
  - Other - See Comments
  - Unknown
- Repair Status Line**
- Completed - Inspected
  - In Use - Fire Management
  - Completed - Ready for Inspection
  - In Progress
  - Repair Needed
  - No Repair Needed
  - Other - See Comments
  - Unknown
- Repair Status Point**
- Completed - Inspected
  - In Use - Fire Management

# Meyer Repair Area - Fallen Leaf

Caldor  
CA-ENF-24030  
October 15, 2021



0 0.35 0.7 1.4 Miles

1:18,000

NAD83 UTM 11N  
Prepared by: GB Team 7 10/14/2021 21:27