




# Meyer Repair Area - Little Round Top

Caldor  
 CA-ENF-24030  
 October 15, 2021



- |   |  |  |
|---|--|--|
| <ul style="list-style-type: none"> <li> Other Property</li> <li> Pump</li> <li> Water Tank</li> <li> Dip Site</li> <li> Helispot</li> <li> Sling Site</li> <li> Drop Point</li> <li> Lookout</li> <li> Road Repair</li> <li> Repair Point</li> <li> Landing or Log Deck</li> <li> Fence - Cut/Damaged</li> <li> Dozer Push</li> <li> Clean Up Area</li> <li> Repeater</li> <li> Hazard</li> <li> Completed Dozer Line</li> <li> Completed Hand Line</li> <li> Completed Mixed Construction Line</li> <li> Completed Road as Line</li> <li> Planned Hand Line</li> <li> Other</li> </ul> | <ul style="list-style-type: none"> <li> Road Repair</li> <li> Fire Edge</li> <li> Contained Line</li> <li> Wildfire Daily Fire Perimeter</li> <li> Forest Service Land</li> <li> Primary Fuel Breaks</li> <li> Secondary Fuel Breaks</li> <li> HazTree Priority Roads</li> </ul> | <p><b>Repair Status Point</b></p> <ul style="list-style-type: none"> <li> Completed - Inspected</li> <li> In Use - Fire Management</li> <li> Completed - Ready for Inspection</li> <li> In Progress</li> <li> Repair Needed</li> <li> No Repair Needed</li> <li> Other - See Comments</li> <li> Unknown</li> </ul> <p><b>Repair Status Accountable Property</b></p> <ul style="list-style-type: none"> <li> Completed - Inspected</li> <li> In Use - Fire Management</li> <li> Completed - Ready for Inspection</li> <li> In Progress</li> <li> Repair Needed</li> <li> No Repair Needed</li> <li> Other - See Comments</li> <li> Unknown</li> </ul> <p><b>Repair Status Line</b></p> <ul style="list-style-type: none"> <li> Completed - Inspected</li> <li> In Use - Fire Management</li> <li> Completed - Ready for Inspection</li> <li> In Progress</li> <li> Repair Needed</li> <li> No Repair Needed</li> <li> Other - See Comments</li> <li> Unknown</li> </ul> |
|---|--|--|



1:24,000  
 NAD83 UTM 11N  
 Prepared by: GB Team 7 10/14/2021 21:37