


SUPPRESSION REPAIR

Caldor
 CA-ENF-24030
 October 15, 2021



- | | | | | |
|---|--|--|---|---|
| <ul style="list-style-type: none"> ● Aerial Hazard ● Check Point ● Dip Site ● Helibase ● Sling Site ● Unimproved Landing Area ● Division Break ● Drop Point ● Staging Area ● Lookout ● Value at Risk ● Other ● Gate ● Bridge ● Water Development or Draft Site ● Structure Wreck ● Stream Crossing | <ul style="list-style-type: none"> ● Resource Location ● Repair Point ● Landing or Log Deck ● Hazard Tree ● Fence - Cut/Damaged ● Dozer Push ● Clean Up Area ● Mobile Weather Unit ● Internet Access ● Repeater ● Restricted Water Source ● Completed Doser Line ● Completed Fuel Break | <ul style="list-style-type: none"> — Completed Hand Line — Completed Mast Construction Line — R - Completed Road as Line — H - Planned Hand Line — Access or Improved Road — Other — Repair Line — Road Repair — Retardant Drop — Route — Internet Edge — Contained Line — Hazard — In Use - Fire Management — In Progress — Repair Needed — No Repair Needed | <ul style="list-style-type: none"> — S1710 — S1740 — S1750 — US - US Route — SR - State Route — RK - Ramp — AK - Access Route — FC - Functionally Classified Other System — EN/Road — TM/Road — HT/Road — Trail — Completed - Inspected — S1100 — S1200 — S1400 — S1500 — S1640 | <ul style="list-style-type: none"> ● Other - See Comments ● Unknown ● Completed - Inspected ● Completed - Ready for Inspection ● In Progress ● Repair Needed ● No Repair Needed ● Other - See Comments ● Unknown |
|---|--|--|---|---|



REPAIR
 OVERVIEW
 Caldor
 CA-ENF-24030
 October 15, 2021

