


# SUPPRESSION REPAIR

## Caldor

CA-ENF-24030  
October 15, 2021



Prepared by: GB Team 7 10/14/2021 21:18

- |  |   |   |  |   |
|--|---|---|--|---|
| <ul style="list-style-type: none"> <li> Aerial Hazard</li> <li> Check Point</li> <li> Dip Site</li> <li> Helibase</li> <li> Sling Site</li> <li> Unimproved Landing Area</li> <li> Division Break</li> <li> Drop Point</li> <li> Staging Area</li> <li> Lookout</li> <li> Value at Risk</li> <li> Other</li> <li> Gate</li> <li> Bridge</li> <li> Water Development or Draft Site</li> </ul> | <ul style="list-style-type: none"> <li> Stream Crossing</li> <li> Road Repair</li> <li> Retardant in Avoidance Area</li> <li> Resource Location</li> <li> Repair Point</li> <li> Landing or Log Deck</li> <li> Hazard Tree</li> <li> Fence - Cut/Damaged</li> <li> Dozer Push</li> <li> Clean Up Area</li> <li> Mobile Weather Unit</li> <li> Internet Access</li> <li> Repeater</li> <li> Hazard</li> <li> Water Source</li> </ul> | <ul style="list-style-type: none"> <li> Restricted Water Source</li> <li> Completed Dozer Line</li> <li> Completed Fuel Break</li> <li> Completed Hand Line</li> <li> Completed Mixed Construction Line</li> <li> Completed Road as Line</li> <li> Planned Hand Line</li> <li> Access or Improved Road</li> <li> Other</li> <li> Repair Line</li> <li> FC - Functionally Classified Other System</li> <li> EMRoad</li> <li> TMRoad</li> <li> HTFRoad</li> <li> Trail</li> </ul> | <ul style="list-style-type: none"> <li> 1100</li> <li> 1200</li> <li> 1300</li> <li> 1400</li> <li> 1500</li> <li> 1600</li> <li> 1700</li> <li> 1740</li> <li> 1750</li> <li> Other</li> <li> US - US Route</li> <li> SR - State Route</li> <li> FC - Functionally Classified Other System</li> <li> EMRoad</li> <li> TMRoad</li> <li> HTFRoad</li> <li> Trail</li> </ul> | <ul style="list-style-type: none"> <li> Completed - Inspected</li> <li> In Use - Fire Management</li> <li> In Progress</li> <li> Repair Needed</li> <li> No Repair Needed</li> <li> Other - See Comments</li> <li> Unknown</li> <li> Completed - Inspected</li> <li> Completed - Ready for Inspection</li> <li> In Progress</li> <li> Repair Needed</li> <li> No Repair Needed</li> <li> Other - See Comments</li> <li> Unknown</li> <li> HazTree Priority/Roads</li> </ul> |
|--|---|---|--|---|



0 0.75 1.5 3 Miles  
1:50,000 NAD83 UTM 11N

REPAIR  
EAST  
Caldor  
CA-ENF-24030  
October 15, 2021